



## FLASHING BASE PLIES





## FLASHING CAP PLIES





NOTES: INSTALL BOOTS ON ALL CAP AND BASE PLY BASE FLASHING CORNER AS SHOWN..



P-30 INSIDE CORNER FLASHING DETAIL

7/13/16

| DRW | CHK | REV |
| JS | KB | 0.1

**ISSUED** 

P-30 SD